

## **National Route 2 Section 1: East of Baden Powell Interchange at Km 29.0 to East of the Broadway Boulevard Interchange at Km 40.202**

### **Using Bitumen Rubber Asphalt to Rehabilitate an Alkali-Silica Affected Jointed Concrete Pavement**

### **Reflection Cracking & Structural Performance**

#### **Authors**

- (1) Strauss PJ, Specialist Consulting Engineer, Pretoria South Africa
- (2) van Heerden JL, Royal HaskoningDHV, Western Cape, South Africa

**Thirty-Sixth Road Pavements Forum  
13 November 2018**



# Contents

## Using Bitumen Rubber Asphalt to Rehabilitate an Alkali-Silica Affected Jointed Concrete Pavement:

### Reflection Cracking and Structural Performance:

#### Contents

1. Project Background
2. Pavement History
3. Current Pavement Condition
4. Remedial Measures Recommended
5. Conclusions

# 1. Project Background




- Once a Concrete Pavement (CP) has reached the end of its structural life;
- Various Remedial Options;
- Road authorities in South Africa were confronted in the 1980's with such a problem;
- 22 kilometre Structurally Failing Jointed Concrete (JC) Section;



# 2. Original Pavement History

## Initial Construction

- The National Route 2 Section 1 Comprising of:
  - Jointed Unreinforced (Plain) Concrete Pavement (JCP); and
  - Flexible Pavement Structures;



- Originally Constructed between 1971 and 1972;

## 2. Original Pavement History

### Structural Failure

- The use of high alkali cement & aggregate high in silica content:
  - in visual cracking by 1975;
  - secondary cracking; and
  - minor structural failures by 1980.
- Alkali Silica Reaction (ASR) - cause - premature failure of the JCP;
- Remedial action - restore & maintain the structural integrity of the concrete pavement;
- Remedial Option Considered - Bitumen Rubber Asphalt (BRA) Overlay;
- Product that was not yet introduced to the local market at the time;

## 2. Original Pavement History

### Design Considerations

- Reflection cracking in an overlay develops above a crack or joint in the layer being overlaid,
- Tension and Shear Stress in the Overlay;
- These stresses can either be caused by:
  - Widening of the contraction joint / crack due to shrinkage of the layer being overlaid i.e. cooling down; or
  - Relative vertical movement due to a rolling wheel that crosses the joint / crack;

## 2. Original Pavement History


### Design Considerations

- The Alkali-Silica Reaction (ASR) in the Jointed Concrete Pavement (JCP) resulted in the:
  - expansion of the aggregate; and
  - development of micro cracking between the coarser particles;
- The concrete pavement structure as a whole, was under compression;
- The net result was that the transverse contraction joints closed up and were not functional anymore as a result of the expansion effect of the ASR.

## 2. Original Pavement History

### Design Considerations

- In the absence of a Falling Weight Deflectometer (FWD) in the 1980's, a modified Benkelman beam was used to measure deflection and RVM;
- a Geophone attached 150 mm from the end of the beam, was used to measure the RVM as the wheel load passed across the transverse contraction joint;





## 2. Original Pavement History

### Design Considerations


- The range of RVM, measured on twelve experimental sections, before different overlays options were constructed varied:
  - 0.01 mm to 0.45 mm.

Section Number	Average RVM (mm)	Range of RVM (mm)
1	0.05	0.01-0.08
2	0.07	0.03-0.15
3	0.06	0.03-0.13
4	0.06	0.03-0.13
5	0.07	0.03-0.16
6	0.07	0.02-0.11
7	0.06	0.03-0.18
8	0.19	0.10-0.25
9	0.35	0.22-0.45
10	0.30	0.22-0.38
11	0.35	0.22-0.45
12	0.15	0.08-0.21

## 2. Original Pavement History

### Experimental Overlay Options

- Keeping this in mind, several experimental overlay options were considered including:
  - Continuously Reinforced Concrete (CRCP);
  - Crushed Stone Base with an Asphalt Wearing Course;
  - Varying thickness of Asphalt with different types of Interlayers;
  - Chip Seals with Bitumen-Rubber and Pen-Grade Bitumen; and
  - Open-Graded Asphalt with Bitumen-Rubber as Binder.



## 2. Original Pavement History


### Experimental Overlay Options

- Since overlaying of a JCP with the experimental overlay options, had not yet been attempted at the time in South Africa, it was decided to:
  - First build Different Experimental Sections;
  - Model their Behaviour;
  - Monitor their Performance over a Short Period; and
  - Building the most Cost Effective and Practical Solution


## 2. Original Pavement History

### Experimental Overlay Options

- Subsequently twelve different experimental overlay sections were constructed to determine the most cost effective and practical solution.




### Schematic Lay-out of the Experimental Sections Completed in 1983



## 2. Original Pavement History

### Experimental Overlay Options



- **01: 30mm Asphalt with Bitumen-Rubber as Binder;**
- 02: 40mm Relatively Stiff HMA with Pen Grade Bitumen;
- 03: 40mm HMA on Woven Geo-Fabric;
- 04: 40mm HMA on Non-Woven Geo-Fabric;
- 05: 40mm HMA on a Bitumen-Rubber Chip Seal;
- 06: Varying Thick HMA on a Bitumen Chip Seal;
- 07: 40mm HMA on 200mm and 150mm thick Crushed Stone Base;
- 08: 150mm and 125mm JCP;
- **09: 150mm bonded Continuously Reinforced Concrete;**
- 10: 125mm and 100mm Continuously Reinforced Concrete;
- 11: 25mm Asphalt with Bitumen-Rubber as Binder on HMA of varying thickness.
- 12: 30mm Asphalt with Bitumen-Rubber as Binder (RA);

## 2. Original Pavement History


### Performance of Experimental Sections

- The first barely visible reflection cracks appeared 3 years after the experimental overlays were initially constructed (2x10<sup>6</sup>E80's);
- Extensive cracking was observed after about 6 years (4x10<sup>6</sup>E80) of service;
- The Bitumen Rubber Asphalt (BRA) and the HMA with interlayer showed superior performance, when compared to the other surface overlay option;
- This already indicated that stress reduction at the contact between the overlay and the JCP was critical;

## 2. Original Pavement History

### Performance of Experimental Sections

- It became clear that relative vertical movement at the transverse contraction joints, had to be taken into consideration, when designing an overlay to reduce the risk of reflection cracking.



### Degree of Reflection Cracking for some Experimental Sections

## 2. Original Pavement History

### Repair & Rehabilitation Strategy

- Based on data obtained from the experimental sections, the performance of the different overlay options was compared.
- Although the CRC showed the best performance, the most cost effective and practical solution to rehabilitate the failing JCP:
  - Replace only Severely Damaged Transverse Contraction Joints:



The concrete on both sides of the joints were removed to full depth and replaced with new concrete



## 2. Original Pavement History

### Repair & Rehabilitation Strategy

- Apply a Bitumen Rubber Single Seal;

sealing the concrete off from the ambient environmental conditions, mainly preventing the exposure to moisture and allow the concrete to dry out.

also served as a stress absorbing inter layer.

- Construct 40 mm Bitumen Rubber Asphalt Semi Open Graded (BRASO) with a high binder content (8.1%).

## 2. Original Pavement History

### Repair & Rehabilitation Strategy

- Rehabilitation was subsequently completed in 1986;
  - the expected life: 8 years or  $6 \times 10^6$  E80's before significant reflection cracking would start occurring.
- Serious maintenance or even rehabilitation was expected after only 12 years of traffic;
- The above measures could be regarded as successful, as since 1986, no major remedial measures had to be performed to improve and/or restore the structural or functional properties of the road;
- The current condition of the road has however now, after 32 years, deteriorated to an extent to warrant maintenance measures.

# 3. Current Pavement Condition


## Terms of Reference

- Royal HaskoningDHV was subsequently appointed by the South African National Roads Agency SOC Ltd (SANRAL) in September 2016:
  - assess the serviceability and structural integrity;
  - investigate and recommend the most appropriate periodic maintenance.

# 3. Current Pavement Condition

## Pavement Condition Assessment

- a Profilometer survey was conducted with a DYNATEST RSP MK3 – ASTM (Class 1) profiler, which produced the following outputs:
  - International Roughness Index (IRI) – [mm/m or m/km];
  - Rutting [mm];
  - Mean Profile Depth (MPD) [mm];
  - Gradient & Cross fall; and
  - JPEG Images at 2 m intervals (down and front images)
  
- The visual condition was thereafter recorded in detail from the profilometer survey outputs as part of the initial assessment.





# 3. Current Pavement Condition

## Transverse Reflection Cracks

- Transverse reflection cracks were observed in the Bitumen Rubber Asphalt at a regular four-meter interval, across all four lanes of the dual carriageway;
- Transverse cracks were caused by a combination of:



- Relative Vertical Movement, due to action of rolling wheels that crosses the transverse contraction joints; coupled
- Warping and Curling effect of the concrete slabs (still in state of compression) under high and low pavement temperatures; and



- Loss of bond between the concrete and the bitumen rubber asphalt.

# 3. Current Pavement Condition

## Transverse Reflection Cracks

- Most of the transverse cracks have been sealed but a number of secondary cracks developed mainly in the slow lane, in addition to the transverse cracks.



# 3. Current Pavement Condition

## Loss of Bond between the Asphalt and Concrete

- Lateral movement of the sealed transverse cracks was also observed;



This indicates a loss of bond between the concrete and the asphalt surface overlay

- Confirmed during the coring and when the asphalt surfacing was removed from the concrete slab at two transverse contraction joints;



Approximately 80 per cent of the 100 mm diameter composite cores displayed delamination of the asphalt surfacing from the concrete



# 3. Current Pavement Condition

## Loss of Bond between the Asphalt and Concrete

- The loss of bond between the Bitumen Rubber Asphalt overlay and the old Jointed Concrete Pavement, occurred due to the:
  - Migration of moisture up, through the contraction joints (spaced at 4m intervals);
  - Accumulation of moisture at the interface between the concrete and the bitumen rubber single seal (stress absorbing inter layer);
  - Horizontal movement of moisture due to the action of traffic loading (rolling wheels) over time;
  - Warping and Curling effect of the concrete slabs (still in state of compression) under high and low pavement temperatures.



# 3. Current Pavement Condition

## Condition of the Concrete

- Concrete cores confirmed that the concrete in general, was still in a good structural condition, except at the joints where some of the cores showed longitudinal cracking at various depths below the surface;



- Concrete from patches that were completed in 1986, to repair severely damaged transverse contraction joints, were found to be in a structurally sound condition.



# 3. Current Pavement Condition

## Rut Depth Measurements

- Rut depth measurements were continuously measured with the DYNATEST RSP MK3 ASTM (Class 1) Profiler in November 2016:



- Summary Outer Wheel Path Rutting (Eastbound) (2016 Measurements)

Lane		Chainage	Average (mm)	P95 <sup>th</sup> (mm)
Fast Lane	Jointed Concrete Pavement	17.8 - 39.4	3.8	8.4
Slow Lane	Jointed Concrete Pavement	17.8 - 39.4	5.0	10.4

- Summary Outer Wheel Path Rutting (Westbound) (2016 Measurements)

Lane		Chainage	Average (mm)	P95 <sup>th</sup> (mm)
Fast Lane	Jointed Concrete Pavement	39.4 – 17.5	3.9	9.1
Slow Lane	Jointed Concrete Pavement	39.4 – 17.5	4.6	10.3

Rutting is only now touching warning levels



Contract: NRA/N\_002-0-0-2017-0-F, km 17.47 to km 39.511  
Average 10 meter Rut Depth  
Direction: East - Slow Lane - Left Wheel Path - 2016  
page 20

Contract: NRA/N\_002-0-0-2017-0-F, km 17.47 to km 39.511  
Average 10 meter Rut Depth  
Direction: East - Slow Lane - Right Wheel Path - 2016

# 3. Current Pavement Condition

## Riding Quality Measurements


- Riding quality measurements were continuously measured with the DYNATEST RSP MK3 ASTM (Class 1) Profiler in November 2016:

- Summary 100m IRI Measurements (Eastbound) (2016 Measurements)


Lane		Chainage	Average	P95 <sup>th</sup>
Fast Lane	Jointed Concrete Pavement	39.4 – 17.5	1.1	1.6
Slow Lane	Jointed Concrete Pavement	39.4 – 17.5	1.5	2.0

- Summary 100m IRI Measurements (Eastbound) (2016 Measurements)

Lane		Chainage	Average	P95 <sup>th</sup>
Fast Lane	Jointed Concrete Pavement	39.4 – 17.5	1.2	2.0
Slow Lane	Jointed Concrete Pavement	39.4 – 17.5	1.6	2.8



Contract: NRAN.022-0-0-2017-9F, km 17.47 to km 38.81  
 Average 100 metre IRI value  
 Direction: East - Slow Lane - Left Wheel Path - 2016



Contract: NRAN.022-0-0-2017-9F, km 17.47 to km 38.81  
 Average 100 metre IRI value  
 Direction: East - Slow Lane - Right Wheel Path - 2016

# 3. Current Pavement Condition

## Condition of the Composite Pavement Structure

- The condition of the Jointed Concrete Pavement in general indicated very little signs of structural distress.



- The obvious presence of reflective cracking of the concrete joints in the asphalt surface overlay, had been attended, with crack sealant and the majority of these seals are still functional;
- Remedial measures were therefore mainly required to address:
  - Condition of the Aged; and
  - De-bonded Bitumen Rubber Asphalt Surface Overlay;

# 4. Remedial Measures Recommended

## Design Philosophy / Strategy

- Remove the deboned Bitumen Rubber Asphalt and 14 mm Stress Absorbing Membrane Interlayer;
- Repair only Severely Damaged Transverse Contraction Joints; (Partial depth repairs / joint spall repairs)
- Design and Construct a New Asphalt Surface Overly:
  - with improved binder elasticity and relaxation properties to accommodate;  
  
warping effect of the concrete under high pavement temperatures;  
curling effect of concrete at low pavement temperatures;
  - that will be resist deformation (rutting) at free-flowing highway speeds;
  - that will be impermeable to the ingress of water;

## 4. Remedial Measures Recommended

### Design Philosophy / Strategy

- Provide adequate bond strength between the new asphalt surface overly and the old jointed concrete pavement structure;
  - Removing oxidised concrete and texturing the surface to promote bond strength;
  - Applying new generation Rapid Set Tack with Adhesion Promoter;
- Provide superior wet weather skid resistance, spray & noise reduction Surfacing.

## 4. Remedial Measures Recommended

### Implementation of Recommended Remedial Measures

- 50 mm Bitumen Rubber Asphalt Surface Overlay;
- Ultra-Thin Friction Course;



# 5. Conclusions

## Summary and Conclusions

- Bitumen rubber asphalt can successfully be used as a surface overlay on top of a distressed jointed concrete pavement;
- It is however important to consider, not only the initial properties of the binder used at the time of construction, but also the change in characteristics over time such as:
  - Adhesion / Bond Strength;
  - Flexibility;
  - Resiliency; and
  - Stiffness

As the Bitumen Rubber Asphalt overlay ages with time.